



Fig. 1

Fig. 2








Fig. 4

AMARDO OF




Fig. 5

Fig. 6




Fig. 7





Fig. 8

## LUMINOSITY MEASUREMENT RESULTS

1)			(h c
	VEHICLE A (AIR CONDITIONER IS OFF)	VEHICLE A (AIR CONDITIONER IS ON)	VEHICLE B (AIR CONDITIONER IS OFF)
BEFORE GROUND MOUNTING	59800	53400	52600
AFTER GROUND MOUNTING	61800	59000	53900

(b)






Fig. 9




Fig. 10




Fig. 11




Fig. 1




Fig. 13




Fig. 14

Fig. 15





Fig. 16








Fig. 18





Fig. 19






Fig. 21





Fig. 22



MAXIMUM OUTPUT (P S)	P1=229.3	P2=233. 7	P3=236.6
MAXIMUM TORQUE (kg-m)	T1=26.97	T2=27.01	T3=27.82
TEST RESULTS	GROUND SYSTEM IS NOT MOUNTED	THROTTLE BODY IS NOT GROUNDED	THROTTLE BODY IS MOUNTED
MEASUREMENT CONDITIONS		GROUND SYSTEM	GINOGNE

Fig. 2